

**Subject: Service Champ Cartridge filter CF5839/WP981**

**Ref: GM 1.4L – 1.8L Engine Oil Cartridges – Vehicles with HENGST or UFI Oil Filter Adapters**

GM Vehicles with 1.4L-1.8L engines may come from the factory with one of two oil filter adapters (OFA). These two adapters are almost identical in outward appearance with the exception of the vendor name on the cast aluminum housings and the injection molded nylon caps. They DO NOT use the same cartridge filters. See Photos below.



HENGST Housing and Filter Cartridge



UFI Housing and Filter Cartridge

The most common OFA is manufactured by and has the name HENGST in raised letters on the cast aluminum housing and nylon cap. These OFA's use the ACDelco PF2257G / Service Champ CF5839/WP981 cartridge.

The other OFA housing is made by UFI as identified on the housing and cap. The UFI housing uses ACDelco PF2263G / Service Champ WP1051OE.

The filters required for these two adapters are NOT interchangeable.

The Service Champ e-catalog has been updated. The 2016 printed catalog and all prior Service Champ printed catalogs do not reflect the adapter options for the vehicles below.

This affects the following vehicles:

Year	Make	Model	Engine
2013-2017	Buick	Encore	1.4L
2013-2017	Chevrolet	Sonic	1.4L
2013-2017	Chevrolet	Sonic	1.6L*
2013-2017	Chevrolet	Sonic	1.8L
2013-2017	Chevrolet	Trax	1.4L
2013-2017	Chevrolet	Trax	1.8L
2015-2016	Chevrolet	Cruze	1.4L
2015-2016	Chevrolet	Cruze	1.8L

\* Non-Canada and -U.S.

For more information or purchase, please call Technical Services at 1-800-882-0890 Champion Laboratories is an ISO/TS16949 registered company. The information contained herein is intended to be used as an indication of performance and is not meant to be used as an exact specification. The information is based upon test data and is subject to test and material variability. Changes may occur based upon technology, process and material innovation as Champion Laboratories strives to attain the highest levels of performance and customer satisfaction. These changes may occur without notification.

**Engine and equipment manufacturer's warranties remain in effect when using Service Champ filters**